



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077
Tel/Fax: (800) 220-3675 / (856) 786-5974
<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 042004728
Customer ID: VRTX78
Customer PO:
Project ID:

Attention: Don Heim
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received Date: 02/21/2020 16:30 PM
Analysis Date: 02/21/2020
Collected Date: 02/21/2020

Project: Clara Barton / 62622

Test Report: Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Appendix A to Subpart E

Sample	Location	Volume (Liters)	Area Analyzed (mm ²)	Non Asb	Asbestos Type(s)	#Structures		Analytical Sensitivity (S/cc)	Asbestos Concentration	
						≥0.5μ < 5μ	≥5μ		(S/mm ²)	(S/cc)
B-01 042004728-0001	Room 300A	1805.00	0.0504	3	None Detected	0	0	0.0042	<20.00	<0.0042
B-02 042004728-0002	Room 304	1786.00	0.0504	2	None Detected	0	0	0.0043	<20.00	<0.0043
B-03 042004728-0003	Room 307	1777.00	0.0504	1	None Detected	0	0	0.0043	<20.00	<0.0043
B-04 042004728-0004	Room 307	1786.00	0.0504	1	None Detected	0	0	0.0043	<20.00	<0.0043
B-05 042004728-0005	Room 309	1748.00	0.0504	1	None Detected	0	0	0.0044	<20.00	<0.0044
B-06 042004728-0006	Room 309	1739.00	0.0504	1	None Detected	0	0	0.0044	<20.00	<0.0044
B-07 042004728-0007	Room 310	1739.00	0.0504	2	None Detected	0	0	0.0044	<20.00	<0.0044
B-08 042004728-0008	Room 311	1729.00	0.0504	0	None Detected	0	0	0.0044	<20.00	<0.0044
B-09 042004728-0009	Room 311	1729.00	0.0504	1	None Detected	0	0	0.0044	<20.00	<0.0044
B-10 042004728-0010	Room 312A	1729.00	0.0504	4	None Detected	0	0	0.0044	<20.00	<0.0044
B-11 042004728-0011	2nd Floor Hallway at Room 204	1767.00	0.0504	1	None Detected	0	0	0.0043	<20.00	<0.0043
B-12 042004728-0012	2nd Floor Hallway at Room 206	1748.00	0.0504	1	None Detected	0	0	0.0044	<20.00	<0.0044

Analyst(s)

Nicholas Maslowski (12)

Samantha Rundstrom, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMSL is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. Samples received in good condition unless otherwise noted. The test results meet the requirements of NELAC unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Piscataway, NJ

Initial report from: 02/21/2020 21:53 PM